


COPY

LLOYD'S REGISTER OF SHIPPING



Report No.

8 / 66

Invoice No. L.L.

504393

Port DAR ES SALAAM

1st July, 1966

This is to Certify that

R. D. Johnston

the undersigned Surveyor to this Society did at the request of the Master of the m.v. "Stirlingshire" attend aboard in the stream for the purpose of examining damaged shell plate at aft. end of ship Starboard side, stated to be plate H 1.

The plate was found to be holed and a temporary, bolted on patch repair was carried out and hose tested.

This will enable the vessel to proceed on a coastal voyage Dar es Salaam - Tanga - Mombasa where re-examination and further repairs can be carried out.

R D Johnston

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."