

PT

~~XXXXXX~~

12 AUG 1965

Ship's name "STIRLINGSHIRE"

Port MDB

No. 23544

Last survey date 18.6.65

Class is subject to

local corrosion on sternframe (s.s) and indented shell plate No.10 in 4th below sheer (p.s), indented shell plate etc. No.7 from aft 3rd below sheer (s.s) and set in shell plates G.8 and H.7 (s.s. from aft) being specially examined and dealt with as necessary next drydocking, also to 15 fathoms of chain cable being supplied at the earliest opportunity.

S.R.L. Appendix (as before ~~xxxxxxx~~)

Nature of present survey (afloat ~~and in drydock~~)

Temporary repairs due to leakage in way of midship deep tanks.

Recommendation SUBJECT as above, and to midship deep tank being specially examined and dealt with as necessary on arrival at LONDON where Ship is now proceeding.

As Now Subject.

IN S.R.L. APPENDIX

Sheerstrake plating abreast fore and main masts (p.s) set in.
Shell plating (p & s) indented.
(External cathodic protection fitted 2,64).

© 2020
Lloyd's Register
Foundation