

Ship's Name ~~SS/MS~~ "MANSOOR" LR 521968

Gross tons 4551 Port of Registry Karachi Port Karachi

Date of build 6-1940 Is there a rpt. 8? No Rpt. No. KRH/1157

No. of visits One First date & Last date 10-5-66

Interim Cert. issued & copy herewith? Yes Damage rpt. issued & copy herewith? No Last rpt. (H.Q. only) *KRH 1074*

Date of completing rpt. 12-5-66 Surveyed at, if different from Port above -

Is a rpt. 9A attached? No MN 333 Nature of survey Cond. of class concerning Starboard boiler.

Survey fees Damage fee Expenses

Rs 150/- Rs 8/-

S.A. fee

DOCKING

Propeller Sea connections Oil gland

Wear down of stern bush (if relined, state clearance before and after)

Fastenings

Has screw/tube shaft been drawn?

Date of examn.

Has shaft been changed?

Has shaft now fitted been previously used?

Has shaft now examined/fitted a continuous liner? Approved oil gland?

BOILERS OPENED UP AND EXAMINED. (Identify by position and state latest date of internal examination of each boiler.)

AUXILIARY, DONKEY OR PRESS (State if oil fired—OF or exhaust gas—EG) MAIN

Air heaters

Superheaters

Safety valves

Mountings, doors and fastenings

Safety valves { Sat adjusted to { Spt

Boiler securing arrangements

Main economisers

Steam heated steam generators

Forced circulating pumps

Have saturated steam pipes in cylindrical boiler smoke boxes been examined as required by the Rules?

Exhaust gas heated economisers and their safety valves

Steam generator safety valves adjusted to

Funnel

Were oil burning system & remote controls examined in accordance with rules?

I recommend that the machinery of this ship remain as classed with/without fresh record of MBS 2/66 as previously recommended, without the condition in respect of the starboard boiler centre combustion chamber tube and wrapper plates, but subject to any other outstanding conditions of class being dealt with as previously recommended.

(Where conditions of class are recommended to be retained, imposed, amended or deleted, particulars must be stated above and on the interim certificate.)

Date of Committee

Minute

TUESDAY 7 - JUN 1966

*Deferred for ES  
MBS 2-66 without spl. cdn.*

(J. van Son)  
Surveyor to Lloyd's Register of Shipping

FOR CHAIRMAN  
CLASSN. CTTEE

ALSO FOR

SPL FOR

NOTED BY  
CESR

SRL

POSTING

HEADER

CERT

Lloyd's Register  
Foundation

004887-004892-0230

At part or complete Special Surveys those items which are not applicable to the ship are to be cancelled; this need not be done when the machinery is on a continuous survey basis. When any part has been subjected to pressure test this should be stated. Engine parts when referred to by numbers should be counted from forward.

considered that re-examination or repairs should be made before that date a distinguishing mark must be inserted against the item and the circumstances and action taken or recommended described fully under "defects and repairs".

The condition of any item is to be described as "good" only when it has been examined, found or placed in good condition, and is considered to be acceptable until the due date of the next Periodical Examination. Where repairs have been effected or it is

EXAMINATION AND TESTING OF STEAM PIPES (state material)

MAIN  
AUXILIARY  
(over 3" bore)

Have saturated pipes in cylindrical boiler smoke boxes been tested?

Were selected copper pipes annealed?

ELECTRICAL EQUIPMENT

PROPULSION (State Port—P, or Starboard—S)		AUXILIARY
Total kW or kVA		Total kW or kVA
a Generators		l Generators & governors
b Exciters		
c Air coolers		m Motors
d Motors		
e Air coolers		n Switchboards & fittings
f Control gear cables, etc.		o Circuit breakers
g Insulation resistance		p Cables
h Insulating oil test		q Insulation resistance
i Overspeed governors		r Steering gear generators & motors
j Magnetic couplings		s Navigation light indicators
k Air gap		

PARTICULARS OF DEFECTS, REPAIRS, ALTERATIONS, ETC.

S.R.L. No.251:

"Starboard centre combustion chamber tube and wrapper plate (EW 2/66) to be re-examined by 5/66".

The EW repaired tube and wrapper plates specially re-examined at this time and found satisfactory.

It is submitted that the above mentioned condition in respect of starboard boiler now be deleted.

The reason for repairs must be stated and those on account of damage, the alleged cause of which must be given, should be detailed separately from wear and tear repairs. State what action has been taken regarding items which are subjects of class. State also where appropriate, for the information of the Technical Records Dept., the material of the defective item and whether it is a forging, casting or welded fabrication. Any alterations in existing particulars in the Register Book should be reported above.

