

Rpt. 8

WRECK SECTION

Port of GENOA

Date of writing Report 29th Sept., 1959.

Who handed in at Local Office

29-9-59

Received London

No. 13464

Survey held at GENOA

No. of Visits One

First Date & 19

Last Date 19/9/ 19 59

REPORT OF SHIP SURVEYS AND REPAIRS

The Surveyor's attention is drawn to the relevant requirements of Chapters B & C of the Rules.

No. in R.B.

36826

on the XXXX Steel XXX

"AURORA P." ex "ZERMAT"

Tons gross 6467

Built at Sunderland

By Whom

Year 1926 Month 7

Owners "TORTUGA" Compania de Navegacion, Panama

Owners' address (If not already in R.B.)

Managers

Port of Registry Panama

Surveyed Afloat or in Drydock in Drydock Name of Dock Grazie No.3, Genoa

Date of last examn. in Drydock 19/9/59.

N.B.—Any alterations in existing particulars in the Register Book should be reported and underlined.

Last Report: No. 23934 Port Gen

Particulars of Classification (which must be inserted precisely as in Register Book and Supplement)

Surveys must be reported in the terms of the Rules. The nature and extent of Examinations and Repairs (if any) must be stated in detail, the parts examined and their condition being clearly indicated. For Annual, Special or other Condition Surveys the Summary of Examination and Condition on the back of the Report is to be carefully completed and amplified if necessary in the body of the Report. Outstanding items to complete the Survey should be summarised at the end of the Report. The reasons for Repairs must be stated. Repairs on account of Damage (the alleged cause of which must be stated) should be separated from Repairs due to other causes, and, besides being detailed in the body of the Report, should be summarised in the form below. When, at a Special Survey, the Shell and Deck Plating is drilled the results must be reported on Report 8(Dr). Whenever Anchors or Chain Cables are replaced or retested the necessary particulars are to be given on Report 8(Eq) which is to be attached to this Report.

SHIP'S CLASS Date of Special and of Drydocking Surveys, etc.	Machinery
+100A1 with Fbd.	+LMC ES 4/57
SS 4/57 (Dr) 6/48	BS M 12/58
DS 1/59	TS CL 3/57
	SP 4/57.

Give dates and references to any letters relating to this Report.

In damage cases where the Surveyor has not made a special damage report he should state whether he offered his services for this purpose and to whom and why they were declined.

Freeboard as marked on ship and now verified 9 ft 0 ins

Was a damage report made by anyone else? If so, by whom?

EXAMINATION AND REPAIRS AS PER RULE FOR DOCKING.

For parts examined for Docking Survey please see overleaf in Tables 1 & 2.

Note :- The Master stated that the ship was to make one voyage to Japan, for sale to shipbreakers.

Existing Condition of Class.

Heavy corroded shell plate in C strake (SS) in way of No.3 D.B. tank (repaired by means of an electric welded doubling plate Genoa 1/59 to be specially examined and dealt with as found necessary at next drydocking).

This repair was examined and considered to remain efficient.— It is recommended that this condition of Class be retained as above.

Existing item of S.R.L. Appendix.

Indents in shell plating (P. & S).— These indented plates were examined and considered to remain efficient. Nothing done at this time.

CONTINUATION OVER/OR SHEET 2

SUMMARY OF DAMAGE REPAIRS	Shell Plates	Frames	R. Frames	Floors and Bracket Floors	Inner Bottom Plates	Deck Plates	Beams	Other Items
Renewed								
Removed and Faired or Repaired								
Faired or Repaired in place								

Has a Survey also been held on machinery of the Ship? yes

yes

Is Classification Certificate required? If so, to be sent to NO

If so, is the Report sent now, or when will it be sent? now

now

Has Interim Certificate been issued? yes.

GENERAL OBSERVATIONS, OPINION AND RECOMMENDATION AS TO CLASS

State clearly what alteration, if any, is suggested to be made in the existing Classification or Survey or other records of the Ship in the Register Book consequent upon this survey; for example:—"to remain as Classed in the Register Book without fresh record of Docking"; "to remain as Classed and to have record of drydocking 1,55"; or "to remain as Classed and to have record of drydocking 1,55, and the notation of S.S. . . . 1,55".

This ship, so far as now surveyed, is eligible, in my opinion, to remain as now Classed with fresh record of Docking 9/59 subject to all conditions at present attached to the ship's Class being dealt with as previously recommended.

DS 9,59. Subj. & app. note as before. J. Tilson 13/10/59.

A. Tilson (A. Tilson). Surveyor to Lloyd's Register of Shipping

Date of Committee

TUESDAY 20 OCT 1959

Minute

DS 9,59, subject

Noted for Header



© 2021

Lloyd's Register Foundation

005038-005046-00 76

TABLE 1

PARTS OF THE SHIP AS INDICATED BELOW HAVE BEEN EXAMINED FOR

DOCKING

SURVEY

Items	Now Examined		Tanks	Now Examined Internally	Now Tested
	YES	NO or NONE			
Shell plating, sternframe and rudder cleaned, examined and recoated in drydock	yes		F.P. Tank		
Rudder lifted	no		A.P. "		
Weather Decks, Superstructures and Casings	yes		D.B. Tanks (indicate Oil Fuel) and Cofferdams		
Hatchways, Covers, closing and securing appliances	yes				
Ventilator coamings, skylights, companionways and closing appliances	yes				
Holds	no		Fresh Water Tanks		
			Deep Tanks		
'Tween Decks	no		Oil Fuel Bunkers and Settling Tanks		
Fore Peak Spaces	no		Side Tanks		
After " "	no		Wing Tanks		
Engine Space	no		Other Tanks		
Boiler "	no		Cargo Tanks (Tankers)		
Under Engines and Boilers	no				
Tunnel and Well	no				
Coal Bunkers	-		Cofferdams		
Chain Locker	no				
Other Spaces	-		Pump Rooms		
			Have Tanks now Examined been Cleaned as Necessary?		
			Have Struts in Cargo Tanks (of Tankers) been removed?		
			Have Tanks been Retested as necessary after completion of any Repairs?		

Have the spaces now surveyed been cleared and cleaned as necessary? **yes**

Have the close ceiling and cargo battens, linings, pipe casings, etc., been removed and replaced as required by the Rules? **no**

Have the bilges been cleaned out and examined? **no** Has cement in bottom been examined? **no**

Has steelwork had rust removed and afterwards been recoated as necessary? **yes**

Were inspection plugs or any insulation removed in insulated spaces for examination of steelwork? **no**

Has a Load Line Survey been held? **no** If so, state which **-**

Have the shell and deck plating been drilled as per Rule? **no** If so, Report 8(Dr) to be attached **-**

Have any alterations to the approved scantlings and arrangements now been effected? **no** If so, report details in body of Report.

NOTE:—Indicate which compartments and/or tanks have been examined or tested by giving the identification numbers and inserting the word "Yes", e.g. Holds: Nos. 1, 2 & 3—Yes; or All—Yes.

TABLE 2

The present condition of the following parts in so far as examined is to be reported:—

Shell plating	Efficient	Ceiling and Cargo Battens	not examined	Sluice Valves examined and found	none
" " in way of side scuttles	not examined	Cement or Asphalt	" "	Air and Sounding Pipes	Good above deck
Rudder and Sternframe	Efficient	Cargo and other Hatchways	Good	Doubling Plates under Sounding Pipes	not examined
Decks	Efficient	Hatches and closing appliances	Good	Masts and Rigging examined and found	Good
Superstructures and their closing appliances	Good	Ventilators, their coamings and closing appliances	Good	Condition, how ascertained (State if wedges removed)	From deck
Coamings and Casings	Good	Companionways and Skylights	Good	Chain Locker	not examined
Beams and Fastenings	not examined	Shell Openings	Good	EQUIPMENT	
Frames	" "	Ash Shoots	-	Equipment Letter	Z
Reverse Frames	" "	Overboard Discharges and Scuppers	Good	Anchors, No. of	Condition not examined
Longitudinals	" "	Freeing ports	Good	Cables (State if now ranged and examined)	not ranged
Transverses	" "	Steering Gear (Main and Auxiliary) examined and found	Good	" length (on board) mean diam.	} stated complete
Floors	" "	Windlass examined and found	Good	" Rule Length Size	
Keelsons	" "	Pumps " " "	not examined	Hawsers and Warps	sufficient
Stringers	" "	W.T. Doors " " "	not examined	State if any Anchors or Chain Cable have now been supplied or retested, if so, complete Report 8(Eq) and attach.	} no

item of S.R.L. Appendix

Have conditions (A) or ~~and (B)~~ of Class (if any) been dealt with? **A : no** See Below
B : no

REMARKS, REPAIRS, Etc. (Contd.)

.....

.....

.....