

311 AUG 1959

Received from Chief Ship Surveyor

SHIP'S NAME "MARSELLA" REPORT Trd. No. 1612

GB

Existing Conditions of Class: NONE.

R.L. Appendix. (~~As before or~~ None)

Structure of Present Survey: (Afloat ~~and in dry dock~~)

Temporary repairs to sheerstrake plate Nos. 4 & 5 (p.s.f) and to deck plating etc. in way on account of collision damage.

Recommendation:

SUBJECT to set in sheerstrake plate Nos. 4 & 5 (p.s.f) and buckled and fractured deck plating in way being specially examined and dealt with as necessary next drydocking, but further ACTION be DEFERRED for Repairs.

SUBJECT



© 2020
28/8/59

Lloyd's Register
Foundation