

10 APR 1958

Chief Engineer Surveyor

Received from Chief Engineer Surveyor

NAME "SEBJAR"

REPORT SOR

No. 41

S. due 6.59 partly held as CS now further advanced.

Doehing P/S screws shafts examined

and the following repairs carried out (due to Wear & Tear & Damage.
Starboard Screws shafts examined. Starboard Screws shaft and one of the
peller blades found bent. New Propeller and new screws shaft fitted with a
tinuous liner now fitted.

IT IS SUBMITTED the vessel is eligible to remain as classed.

with RECORD of survey TS. P. 1.58 and S. (CL) (N) 1.58 as recommended.

new and CS with date when the survey is completed.

See Form T.E.

RB. TS P. jointed liner.
TS. S. (CL)



Lloyd's Register
Foundation

005107-005117-0065