

Received from Chief Ship Surveyor

12 AUG 1957

SHIPS NAME "HOLDERNIDD" REPORT Cff. No. 60170.
D.

Outstanding Conditions of Class: Subject to indented or set in bottom shell plates (p & s.f.) and to defective shell plate in way of No.2 hold (p.s.) (E.W.& doubled 11,56) being examined and dealt with as necessary at the next drydocking.

Endorsement of Class (B) (As before ~~XXXXXX~~)

Nature of Present Survey: (Afloat and in dry dock)

Docking and damage repairs (various causes) and to part of the deferred items as above.
Wear and tear repairs.

Recommendation:

SUBMITTED notation of "DS 7,57" be assigned, SUBJECT to permanent repairs to set over stem and stemplating, shell plates D.2 & E.3 (p.s.f.) also A.5 in 1st strake below sheer (p.s.) as necessary next drydocking, with Endorsement of Certificate.

without other condition but

DS 7,57. Subject
Amended.
Without

ENDORSEMENT OF CERTIFICATE.

Indents in keel plate No.2 (aft) and adjacent strake (p.s.a.).



© 2020

L.R.C.
20-7-57
Lloyd's Register
Foundation