

29 NOV 1956

Received from Chief Ship Surveyor

SHIP'S NAME

"HOLDERNIDD"

REPORT

Mdb.

No. 20833.

JD.

Outstanding Conditions of Class:

Subject to indented or set in bottom shell plates D.2 & E.3 (p.s.f.) and C.1, D.2 & E.3 (s.s.f.) being examined and dealt with as necessary by next drydocking and to permanent repairs being effected to defective shell plate (leakage) in No.2 hold (p.s.) on ship's arrival in the River Tees.

Endorsement of Class (B) (As before of ~~EXXONS~~)

Nature of Present Survey: (Afloat and in dry dock)

Further temporary repairs (E.W. doubler) fitted to defective shell plate in No.2 hold (p.s.).

Recommendation:

SUBMITTED the ship is eligible to remain as classed, SUBJECT to indented or set in bottom shell plates (p & s.f.) and to defective shell plate in way of No.2 hold (p.s.) (E.W. & doubled 11,56) being examined and dealt with as necessary at the next drydocking, with Endorsement of Class (B).

As Now. Subject
Amended.

ENDORSEMENT OF CLASS(B).

Indents in keel plate No.2 (aft)
and adjacent strake (p.s.a.).



© 2020

Lloyd's Register
Foundation

Blk(new)

005118-005131-0020

This
"Whi
it is to b