

Repairs - The regulators of the feed pump and the donkey pump have been taken away to put an intercepter valve between the retaining valve clapper and the boiler.

A third ^{gauge} Cock has been put in accordance with French Law. A valve for surface extraction has been put - and a pipe with a funnel has been put inside the boiler - A Cock with pipe has been put - on the condenser to replenish the losses of fresh water.

The injector has been put for suction to the ballast tank.

Note. The iron plates put upon the bearing in front of the crank MP and upon the bearing in front of the Crank BP are in good condition - A careful survey of this part reveals the fact that they were placed there to hide a defect in the run of this piece.

No crack ^{visible} or fault was discovered.

N.B. - If this Report is copied by Copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or to cause it to show through to the other side.

THE S' TO CE RE



© 2020

Lloyd's Register
Foundation