

6 JAN 1966

SHIP'S NAME

'Phoenixian Star'

PORT

No.

LAST SURVEY DATE

CLASS IS SUBJECT TO

Before this case receives ~~and~~ consideration further information should be obtained from the surveyors:-

1. Was screwshaft crack detected as shaft has been accepted for 4 yearly surveys at per C1102 of the Rules.
2. As the stern bush was renewed 6.65 do a 1.2 mm clearance could surveyor state any unusual cause for the rapid wear down.
3. As we have no information regarding any temporary cables being fitted in holds could surveyor state when these were fitted and also the reason they were fitted.
4. It is concluded that all temporary cables have now been completely disconnected and replaced with cables which comply with the Rules but surveyors should confirm.

24/11

13

6.1.66.