

Vessel entered in dry dock bottom and rudder cl

2m.10.33.

11

Received by Chief Ship Surveyor _____

Received from Chief Ship Surveyor 2 - JUL 1934

VESSEL'S NAME Steel S.K. "ORVICTO"

Rpt. Gms No. 18929

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement." - Extract from Sub-Committee's Report, 24/5/12.)

Nature of Survey Docking

The Grimsbey Surveyors report this vessel placed in dry dock, bottom cleaned and coated and minor repairs effected.

An Echometer sounding apparatus has now been fitted
It is submitted the vessel appears worthy to remain as

classed with record of survey 6.34 as recommended.

100 A1
Stm Yawler
6.34. GMS.



© 1920
J.C.S.

30.6.34
Lloyd's Register
Foundation

005194-005209-0062

classed and to have record of survey 6.34.

ie space for Co

M. of V
on Fel
on, Mo
...
, &c.
w ascert
wedge
...
tter ...
of ...
e if now
... board)
length
Warps
d Running
Register B
classed an