

Anna Rehder

Ham. NWE

396

Before this case receives consideration the Ham. Surveyor might be requested to state whether there are any ~~other~~ special reasons other than the question of the diameter of the screw shaft necessitating its renewal. as recommended

According to the present Rule. the diameter should be 233 $\frac{1}{4}$ in at top of cone. Calculated on the original diameter of the propeller of 3070 $\frac{1}{4}$ in when the vessel was classed with L.R.

As it would appear that the shaft has been skinned up to 234 $\frac{1}{4}$ in any further information they may be able to give will be appreciated regarding this point

Clsy Li Ham:



© 2021

X

Ham. 10.2.47
Lloyd's Register
Foundation

005280 - 005292 - 0178