

BRITISH CORPORATION

Sm,6,49.

23 NOV. 1949

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSELS NAME

JIM M.

REPORT

Hul. No. 56094

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

This vessel is classed BS* (Coasting Service).

A Special Survey Type 1 became due 9.48 when a further Annual Survey was held.

The HULL Surveyors report the vessel placed in dry dock and the greater part of the SPECIAL SURVEY held.

To complete the S.S.:-

Test Oil Fuel Bunkers.

Repairs effected to two fractured shell plates in way of after end of No. 2 Hold (s.s.) and to minor items.

It was noted that a previous repair had been effected to a set in and fractured shell plate (s.s.) poop space with set up deck plating in way, but efficient.

They recommend repairs at Owners' convenience. (B)

The longitudinal bulkheads in holds (p & s) forming wing ballast tanks cut away and compensation fitted to approved attached plans. The W.T. bulkhead between 1 and 2 Holds pierced for common bilge drainage. They recommend suitable modification in the Register Book.

NO CARGO BATTENS ARE FITTED IN HOLDS, THEY RECOMMEND NOTATION BE INSERTED IN R.B.

IT IS SUBMITTED the vessel is eligible to have record of docking survey 9.49 and notation of "Annual Survey 10.49", but ACTION and NOTATION of "ss. Hul.- 10.49" be DEFERRED for completion of Special Survey.

BS* (Coasting Service)

9.49 Hul.

Annual Survey 10.49

ENDORSEMENT OF CLASS (B)

Shell plate poop space (s.s.) etc.
set in and fractured.

AMEND R.B.:

From: 4 EH

To: 3 EH

C.S.S. Records Dept.

to note. *Lawrence shell plates*



John 10/11/49

CARGO BATTENS NOT FITTED



© 2021

TO COMPLETE S.S.:
Test oil fuel bunkers.

Lloyd's Register
Foundation

005311-005317-0078