

115 SEP 1953

Be

ad by Chief Ship Surveyor

Received from Chief Ship Surveyor

P'S NAME "IMPERIAL WINNIPEG"

REPORT

Hfx.

No. 6587

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

This ship is of the T2 type and classed
BS (Tanker - Oils F.P. below 150 F).

The class is subject to indented stem plating
being permanently repaired by next Special Survey.

There is an Endorsement of Class (B).

SPECIAL SURVEY TYPE 3 due 8,55 - Progressive S.S.

The HALIFAX Surveyors report (7,53), this tanker
examined in dry dock and the progressive Special Survey advanced.

On account of various damages, repairs effected
to shell, bulwarks, rudder, etc.

On account of wear and tear, repairs effected to
stem plating, as above, also to numerous fractures in the
cargo tank structure.

They also report docking brackets fitted,
bottom girders altered and additional stiffening fitted in the
fore peak in accordance with plans attached.

IT IS SUBMITTED record of docking 7,53 and
Notation of 'A.S. 7,53' be assigned, without
special condition.

BS (Tanker- Oils F.P. below 150²F).
7,53 Hfx.
A.S. 7,53. Without.

and
C.B.S. Records Dept.
to note.



ENDORSEMENT OF CLASS (B).

Indents in 2nd & 3rd strakes below
sheer (p & s).


OFFICE NOTE:-

T2 Tanker stiffening fitted - N.Yk. 9,52.
DKG. BKTS. FITTED HFX. 7,53.

IT IS FURTHER SUBMITTED the Surveyors be informed
it is concluded that testing only of the tanks, etc. enumerated
under the heading of "Progressive Hull Survey" can be credited
towards this Survey, but this should be confirmed.

MR. J.M. MURRAY TO NOTE.

See 510-52



© 2021

Lloyd's Register
Foundation

29/8/53

Transit
lights are req