

"TRESUS" ex "LAUREL HILL".


REPAIRS. Bottom 4 rows of tubes renewed, remaining tubes, nipples, downcorners etc. expanded. Boiler examined under hydraulic test on completion. Main and auxiliary machinery tried under working conditions.

N.B. Spare propeller to be placed on board first opportunity.

ELECTRICAL EQUIPMENT. examined, tested and found satisfactory. Please see First Entry Reports 4 D. and 13.

water Class Contemplated

Roll 21/1/18.



© 2020

Lloyd's Register
Foundation