

Surveyor

Received from Chief Ship Surveyor

22 MAY 1951

S.S. "SALTFLEET."
E

REPORT

HUL

57373

No.

ks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

ement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and
ing out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points
in the endorsement."—Extract from Sub-Committee's Report, 24/5/52.)

This Vessel is classed B.S.*

ACTION is DEFERRED for examination in dry dock after
grounding.

Indented shell plates, etc. (s.s.) required to be ex-
amined and dealt with as necessary on vessel's return to Goole
from present voyage.

The HULL Surveyors report the Vessel placed in dry dock,
bottom coated and on account of previously reported contact
with pier the indented side and bottom plating, etc. as above,
in way of No. 2 hold (s.s.) dealt with.

In consequence of previously reported grounding, as above,
repairs effected to set up and indented bottom plating, etc.
(p & s) in way of No. 2 hold.

A few indented side shell plates (p & s) recommended
to be further examined and dealt with as necessary at the
next SPECIAL SURVEY.

IT IS SUBMITTED the Vessel is eligible to remain
as classed by the British Corporation with record of
docking survey 4,51 subject to indented shell plates
No. 2 in 2nd below (p.s.) No. 4 in 1st below and
Nos. 3 & 4 in 2nd below (s.s.) being dealt with as
necessary by the next SPECIAL SURVEY, but without
other conditions.

4,51 Goo. Subject.
Without.

~~DELETE FROM SRL.~~
Drydocking (grounding.)

Yail
18.5.51



© 2021

Lloyd's Register
Foundation

005377-005386-0232