

"EMPIRE MIGHT"

F.E.Rpt. Grk. No. 21932.

Before this case receives the consideration of the Committee, the Surveyors should be informed it would appear from the sketch of bulkhead stiffeners with welded end struts in lieu of brackets, forwarded with their report, that the scantlings of the six watertight hold bulkheads have been approved for a height to the 2nd deck only, so that a record of "7BH (Coll to W dk, 6 to 2nd dk), 6 divisional W.T. BH's in upper 'tween dks" should be inserted in the Register Book, but they should state if this is correct.

They should further state if there are any openings in the upper 'tween deck bulkheads and, if so, furnish particulars of the means of closing same.

They should furnish the scantlings of the saloon house forming a forward bridge, so that it may be ascertained whether the length of this superstructure requires to be recorded in the Register Book.

They should also state if hatch covers have been fitted to the 'tween deck hatchways clear of the insulated spaces.

*for bulk  
2/18*



© 2020

*J.C.P.*  
20.8.42.  
Lloyd's Register  
Foundation