

EA

Ship's name "MARWARRI" Port CBO No. 5295
 CHG. 319
 Last survey date 14.1.63

Class is subject to

set up keel plates Nos.2 & 3 forward and to indented shell plates Nos.5 & 6 in 3rd strake below sheerstrake and Nos.4 & 5 in 4th strake below sheerstrake (s.s.f) being specially examined and dealt with as necessary by the next drydocking.

S.R.L. Appendix (as before ~~XXXXXXXXXX~~)

Nature of present survey (afloat and ~~XXXXXXXXXX~~)

Temporary repairs to corroded plating.

Recommendation

SUBJECT as above and to No.4 hold deep tank after bulkhead (corroded) in way of port bilge being specially examined and dealt with as necessary at the next drydocking, also to shell plate J.19 (corroded and leaking) (p.s) being dealt with as necessary by 4,63.

As Now Subject.

IN S.R.L. APPENDIX.

No.3 keel plate from forward slightly set up.



© 2020

Lloyd's Register
 Foundation

005436-005442-0018

005436-005442-0019