

NOTE:- Owners Superintendent stated that ship is to sail direct to River Blackwater

Received from Chief Ship Surveyor

14 NO.

SHIP'S NAME "SAN VITO" REPORT FAL No. 13858

standing Conditions of Class: SUBJECT to indented shell plates G.5, 9, & 10 (p.s.a) being examined and dealt with as necessary by next drydocking.

R.L. Appendix. (As before or None)

ture of Present Survey: (~~Afloat~~ and in dry dock)

Docking: Wear and tear repairs.
Deferred repairs to set in shell plating etc.
(cause not stated).

commendation: SUBMITTED record of DS 10,60 be assigned, subject as above and to set in shell plates H.7, J.8 & 9 and K.8 (p.s from aft) with structure in way being specially examined and dealt with as necessary next drydocking.


DS 10,60 Subject.

OFFICE NOTE.

Chain cable on starboard side renewed 4,60 to Rule size (2. 1/8") S.Q.

NOTE:

The Owners Superintendent states that the ship is to sail to River Blackwater where she is to be laid up.



© 2020

Lloyd's Register
Foundation

005436-005442-0134