

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report 1933 When handed in at London 1933 Port of London

No. in Reg. Book. Survey held at

Date, First Survey

Last Survey

19

19929 on the Wood, Iron or Steel S.S. "Albisola"

TONNAGE

Built at Burntisland

By whom Burntisland S.B. Co. Ltd. When 1927 - 10.

GROSS 4097

Owners

"Corrado" Soc Anon di Nav.

Owners' Address

(if not already recorded in Appendix to Register Book).

UNDER DE. 3871

Managers

NET 2527

Port belonging to Genoa.

Surveyed Afloat or in Dry Dock?

Name of Dock

Destined Voyage

WB=CellDBorDBa

feet; uE&B

feet; f

total capacity tons. FPT tons; APT tons; MT feet tons.

N.B.—All alterations in the existing records should be underlined.

If the Vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Last Report, No. 13952 Port Gen

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements)

CHARACTER
* for Special Survey
Date of last survey and of
Periodical Surveys.Assigned
Survey
When
last
examined.Machinery and Boiler
Surveys
(including date of N.B. if any).

+100 A1 6.35

+LMC 12.31

S.S. P.NE. No 1-31

BS. 3-35

C.L. 3-34

DUAL CLASS.

Society's Freeboard (if assigned) as painted on Ship and now verified ft. ins.

Was a damage report made by anyone else? If so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE, FOR

SUMMARY OF DAMAGE REPAIRS:—

Renewed
Removed and Fair'd or Repaired
Fair'd or Repaired in place

Shell Plates.

Frames.

R. Frames.

Floors.

Beams.

Str. Plates.

Dk. Plates.

Other Items:—

PRESENT CONDITION OF THE

Decks	State if Tanks have been examined inside	Air and Sounding Pipes	Copper, or Y.M. of Wood Vessels (state if on rett). When put on, Month Year
Caulking of Decks	State if Tanks now tested	Dblng. Plates under Sounding Pipes	Boats
Coamings	Bulkheads	Engine Room Skylights	Masts, Yards, &c.
Beams & Fastenings	Ceiling	Coal Bunkers, Open'gs, Lids, &c.	Condition, how ascertained (State if wedges removed)
Outside Plating	Cement or Asphalt (State which.)	Oil Bunkers	Sails
" " in way of sidelights	Rudder	Scuppers	Equipment letter
Breasthooks	Steering gear and its connections	Cargo Hatchways	Anchors, No. of
Transoms	Windlass	Hatches	Chain Locker
Frames	Have pumps now been examined and found efficient?	Planking of Wood Vessels	Cables (State if now ranged) (on board) length mean diamr. Rule length size
Reverse Frames	Have Sluice Valves now been examined and found efficient?	Caulking ditto	Hawser & Warps
Longitudinals	Have Watertight Doors now been examined and found efficient?	Treenails ditto	Standing and Running Rigging
Transverses	Have Ventilators and their Coamings been examined and found efficient?	Breasthooks & Stemson ditto	
Floors		Transoms Pointers, & Crutches ditto	
Keelsons		Timbers of Frame at openings ditto	
Stringers		Ditto Ditto at other places ditto	
Inner Bottom Plating		Stringers, Clamps & Shelves ditto	
		Salting ditto (State if examined.)	

General Observations, Opinion as to Class, Recommendation, &c.:—

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,24," or "to remain as classed and to have record of survey, 1,24, and the notations of ss No. 1-24 and ptND24, &c."

Survey Fee (per Section 29) £

Fees applied for,

Special Damage or Repair Fee (if any) (per Sec. 29) £

Received

Travelling Expenses (if chargeable) £

Second Surveyor's Fee (if any) £

Committee's Minute TUE. 8 OCT 1935

Character Assigned



© 2021

Lloyd's Register
Foundation