

No. of Bilge pumps 2 Diameter of ditto $2\frac{1}{8}$ Stroke $10\frac{1}{2}$ Can one be overhauled while the other is at work yes
00 1¹/₂" - 5¹/₂" x 6" No. and size of Suctions connected to bo


Lorcan

Jis 1873)

It is submitted that this case be deferred until a report is received to the effect that the main boiler safety valves have been adjusted under steam.

BD.

M.S.
6.3.01



Thickness $1\frac{1}{32}$ Range of tensile strength $60-70$

Diameter of rivet holes in long. seams $1\frac{1}{32}$ " Pitch of rivets $8\frac{9}{16}$ "

Thickness $1\frac{1}{32}$ Range of tensile strength $60-70$

Diameter of rivet holes in long. seams $1\frac{1}{32}$ " Pitch of rivets $8\frac{9}{16}$ "

005489-005502-0140

Gap of plates or width of butt str