

Received by Chief Engineer Surveyor

Received from Chief Engineer Surveyor

110 SEP 1957

SHIP'S NAME SOLARIUM.

REPORT CFF

No. 60207

The remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement.")—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey REPAIRS TO ENGINES AND BOILERS DUE TO DAMAGE THROUGH

CS due 2.57 now completed.

DBS due 8.57, now held

Docking

SRL Surveyor reports that when vessel left DD, propeller struck quay wall + was temp. repaired, + recommends that it be again examined + dealt with as necessary next DD.

SRL Surveyor reports all <sup>B</sup>DB furnaces distorted + surveyor recommends they be specially examined and dealt with as necessary ~~next~~ by 2.58

It is submitted the record of DBS 8.57 be withheld pending the necessary examination + repairs.

It is submitted that  
this vessel is eligible for  
THE RECORD.

CS 8.57, subject as  
now recommended.



© 2010

9 SEP 1957  
Lloyd's Register  
Foundation

005512-005517 0077