

liners are fitted, is the shaft lapped or protected between the liners
plain as per rule 6.47"

No

Length of


cf "Parrea"

Hull Rpt No 23889

It is submitted that the Hull Surveyors should be requested to state to what pressure they adjusted the safety valves.

It is concluded that easing gear has been fitted to the safety valves although it is not stated on their report.

Am 20/6/11



© 2020
Lloyd's Register
Foundation

005585-005601-0139