

coated. Port side cables ranged - five lengths supplied and connected to anchor

2m,10,43.

1

Sent to Chief Surveyors.....

Received from Chief Surveyors.....

19 MAY 1944

VESSEL'S NAME "WALTER JENNINGS" REPORT N.Ns. No. 5700

For the CHIEF SHIP SURVEYOR ~~and CHIEF ENGINEER SURVEYOR~~

In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey Docking

~~17.5.44~~

Noted.

18.5.44. *was*



© 2021

Lloyd's Register
Foundation

005635-005643-0148

Reverse Frames

Longitudinals

Check

Have Sluice Valves been examined and found effi-

Caulking

Anchors, No. of