

REPORT OF SURVEY FOR REPAIRS, &c. DISCLOSED
BAY No 266

Date of writing Report 19... When handed in at Local Office 19... Port of London

No. in Survey held at... Date, First Survey... Last Survey... 3 1944
Reg. Book.

33186 on the Wood, Iron or Steel t.s.s. "Siangwo" By whom H. K. & W. Hamlin D.B. Co. Ltd. When 1926

TONNAGE :-
GROSS 2595
UNDER DK. 1130
NET 1515
Built at Hong Kong
Owners Indo China L.N. Co. Ltd.
Managers
Owners' Address
Port belonging to Hong Kong

Surveyed Afloat or in Dry Dock? Name of Dock... Destined Voyage...

Cell DBor DBa feet; uE & B... feet; f... feet
total capacity tons. FPT tons; APT tons; MT... feet tons.

Only alterations in the existing records of tanks should be inserted.
N.B. All alterations in the existing records should be underlined.

Last Report, No. 6898 Port SNG

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements)
CHARACTER: * for Special Survey Date of last Survey and of Periodical Surveys. Machinery and Boiler Surveys (Including date of N.B., if any).
A1 LMC 7-37
2-41 BS 11-40
as 8th No 3-7-37 TS OG 11-40
For service between Hong Kong and Canton
NO LATER SURVEY REPORTED

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined
Society's Freeboard (if assigned) as painted on Ship and now verified ft. ins.

Was a damage report made by anyone else? if so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE, FOR

SUMMARY OF DAMAGE REPAIRS :-	Shell Plates.	Frames.	R. Frames.	Floors and Bracket Floors	Beams.	Inner Bottom Plates.	Dk. Plates.	Other Items :-
Renewed ...								
Removed and Fair'd or Repaired								
Fair'd or Repaired in place ...								

PRESENT CONDITION OF THE		
Decks	Bulkheads	Engine Room Skylights
Caulking of Decks	Ceiling	Coal Bunkers, Openings, Covers, &c.
Coamings	Cement or Asphalt	Oil Bunkers
Beams & Fastenings	Rudder	Seuppers
Outside Plating	Steering gear and its connections	Cargo Hatchways
" " in way of sidelights	Windlass	Hatches
Frames	Have pumps been examined and found efficient?	Planking
Reverse Frames	Have Sluice Valves been examined and found efficient?	Caulking
Longitudinals	Have Watertight Doors been examined and found efficient?	Treenails
Transverses	Have Ventilators and their Coamings been examined and found efficient?	Breasthooks & Stems
Floors	Air and Sounding Pipes	Transoms, Pointers & Crutches
Keelsons	Doubling Plates under Sounding Pipes	Timbers of Frame at openings
Stringers		" " at other places
Inner Bottom Plating		Stringers, Clamps & Shelves
Have the Tanks been examined internally?		Salting (State if examined.)
Have the Tanks been tested?		
		Copper, or Y.M. (State if on Felt.)
		When fitted, Month Year
		Boats
		Masts, Yards, &c.
		Condition, how ascertained (State if wedges removed.)
		Equipment letter
		Anchors, No. of
		Cables (State if now ranged)
		" length mean diamr. (on board.)
		" Rule length size
		Chain Locker
		Hawsers & Warps
		Standing and Running Rigging
		Sails

General Observations, Opinion as to Class, Recommendation, &c. :-
State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example :- "to remain as classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,38," or "to remain as classed and to have record of survey, 1,38, and the notations of ss No. 1-38."

Survey Fee (per Section 29)	£	:	:	Fees applied for,
Special Damage or Repair Fee (if any) (per Sec. 29)	£	:	:	19
Travelling Expenses (if chargeable)	£	:	:	Received by me,
Second Surveyor's Fee (if any)	£	:	:	19

Committee's Minute... TUES. 28 MAR 1944
Character Assigned... OMIT CLASS ON RE-PRINT.