

Rpt. 8.

DISCLOSED

(Received at London Office)

No. 7427

REPORT OF SURVEY FOR REPAIRS, &c.

Date of writing Report 19... When handed in at Local Office 19... Port of Cebu P.I.

No. in Reg. Book. Survey held at Date, First Survey Last Survey 4712 1940
69520 on the Wood, Iron or Steel Steamer 'Amagisan Maru'
TONNAGE:- Built at Mus. Tama By whom Mitsui Bussan Kaisha Co. When 1933 12
GROSS 1630 Owners Mitsui Bussan Kaisha Co. Owners' Address (if not already recorded in Appendix to Register Book).
6836 Managers Port belonging to Kobe
4711

d Afloat or in Dry Dock? Name of Dock Destined Voyage

Capacity tons. FPT tons. APT tons; MT feet tons. feet; uE&B feet; f feet

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements)

Only alterations in the existing records of tanks should be inserted.
All alterations in the existing records should be underlined.

Report, No. 3108. Port MAN.

Surveys, when held, must be reported in detail and seriatim in the terms of the Rules and items remaining to the Survey should be summarised. State clearly the cause of Repairs, if any, and, in detail, the nature and Examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) separated from Repairs due to other causes; and besides being detailed in the body of the report, should be stated in the form shown below. Whenever the replacement of Anchors or Chains is reported the particulars clearly stated in the space provided on the back of this form. State also the dates and initials of any letters of this case.

cases where the Surveyor has not made a special damage report he is required to state whether he has made his services for this purpose and to whom and why they were declined

Society's Freeboard (if assigned) as painted on Ship and now verified ft. ins.

Was a damage report made by anyone else? if so, by whom?

OR EXAMINATION AS PER RULE, FOR

DAMAGE REPAIRS :-	Shell Plates.	Frames.	R. Frames.	Floors and Bracket Floors	Beams.	Inner Bottom Plates.	Dk. Plates.	Other Items :-
and Paired or Repaired								
or Repaired in place								

CONDITION OF THE

Bulkheads	Engine Room Skylights	Copper, or Y.M. (State if on Felt.)
Ceiling	Coal Bunkers, Openings, Covers, &c.	When fitted, Month Year
Cement or Asphalt	Oil Bunkers	Boats
Rudder	Scuppers	Masts, Yards, &c.
Steering gear and its connections	Cargo Hatchways	Condition, how ascertained (State if wedges removed.)
Windlass	Hatches	Equipment letter
Have pumps been examined and found efficient?	Planking	Anchors, No. of
Have Sluice Valves been examined and found efficient?	Caulking	Cables (State if now ranged)
Have Watertight Doors been examined and found efficient?	Treenails	length mean diamr. (on board)
Have Ventilators and their Coamings been examined and found efficient?	Breasthooks & Stemson	Rule length size
Air and Sounding Pipes	Transoms, Pointers & Crutches	Chain Locker
Doubling Plates under Sounding Pipes	Timbers of Frame at openings	Hawsers & Warps
	Stringers, Clamps & Shelves	Standing and Running Rigging
	Salting (State if examined.)	Sails

ul Observations, Opinion as to Class, Recommendation, &c.:-

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon survey, thus, for example: "to remain as classed in the Register Book without 'fresh record of Survey,'" "to remain as classed and to have record of 1,38," or "to remain as classed and to have record of survey, 1,38, and the notations of ss No. 1-38."

er Section 29)	£	:	:	Fees applied for,
Special Damage or Repair Fee (if any) (per Sec. 29)	£	:	:	10
Travelling Expenses (if chargeable)	£	:	:	Received by me,
Second Surveyor's Fee (if any)	£	:	:	10


Surveyor to Lloyd's Register of Shipping.

Committee's Minute

Character Assigned

TUE. 4 MAR 1941

See Enla. Rpt 3108



Lloyd's Register Foundation

005740-005755-0006