

REPORT OF SURVEY FOR REPAIRS, &c.

Date of writing Report 19... When handed in at Local Office 19... Port of London

No. in Reg. Book Survey held at Date, First Survey Last Survey 4/39 19

83255 on the Wood, Iron or Steel Twin Sc. "SENATOR" (No. of Visits)

TONNAGE:- Built at Gothenburg By whom Gotaverken A/B When 1934 - 3

GROSS 6589 Owners Stavanger Taulkrederi A/S Owners' Address

UNDER DK. 5971 Managers Port belonging to Stavanger

NET 1002 Surveyed Afloat or in Dry Dock? Name of Dock Destined Voyage

Cell DBor DBa feet; u & B feet; f feet Particulars of Classification (which must be inserted precisely as in Register Book & Supplements)

total capacity tons. FPT tons; APT tons; MT feet tons. Only alterations in the existing records of tanks should be inserted.

N.B.—All alterations in the existing records should be underlined. N. B.—All alterations in the existing records should be underlined.

ast Report, No. 12184 Port Got

damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined

Was a damage report made by anyone else? If so, by whom? PAIRS, OR EXAMINATION AS PER RULE, FOR

CHARACTER. * for Special Survey, Date of last Survey and of Periodical Surveys.	Machinery and Boiler Surveys (including date of N.B., in any).
+ 100 A1 6.37	+ LMC 3.34 DBS 1.39 CL 12.38

Carrying petroleum in bulk
Oil Engine

Society's Freeboard (if assigned) as painted on Ship and now verified

MARY OF DAMAGE REPAIRS:—	Shell Plates.	Frames.	R. Frames.	Floors and Bracket Floors	Beams.	Inner Bottom Plates.	Dk. Plates.	Other Items:—
Renewed								
Removed and Faired or Repaired								
Faired or Repaired in place								


PRESENT CONDITION OF THE	Bulkheads	Engine Room Skylights	Copper, or Y.M. (State if on Felt.)
ing of Decks	Ceiling	Coal Bunkers, Openings, Covers, &c.	When fitted, Month Year
ngs	Cement or Asphalt	Oil Bunkers	Boats
& Fastenings	Rudder	Scuppers	Masts, Yards, &c.
Plating	Steering gear and its connections	Cargo Hatchways	Condition, how ascertained (State if wedges removed)
in way of sidelights	Windlass	Hatches	Equipment letter
se Frames	Have pumps been examined and found efficient?	Planking	Anchor, No. of
adinals	Have Sluice Valves been examined and found efficient?	Caulking	Cables (State if now ranged)
verses	Have Watertight Doors been examined and found efficient?	Treenails	length mean diamr. (on board)
ns	Have Ventilators and their Coamings been examined and found efficient?	Breasthooks & Stemson	Rule length size
ers	Air and Sounding Pipes	Transoms, Pointers & Crutches	Chain Locker
Bottom Plating	Doubling Plates under Sounding Pipes	Timbers of Frame at openings	Hawsers & Warps
he Tanks been examined internally?		" " at other places	Standing and Running Rigging
he Tanks been tested?		Stringers, Clamps & Shelves	Sails
		Salting (State if examined.)	

General Observations, Opinion as to Class, Recommendation, &c.:

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,38," or "to remain as classed and to have record of survey, 1,38, and the notations of ss No. 1-38."

Survey Fee (per Section 20)	£	Fees applied for,	19
Special Damage or Repair Fee (if any) (per Sec. 20)	£	Received by me,	19
Travelling Expenses (if chargeable)	£		
Second Surveyor's Fee (if any)	£		

Committee's Minute Character Assigned Write new class 8 APR 21 1939 Deferred



005756-005778-0226