

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report 19... When handed in at Local Office 19... Port of London

No. in Reg. Book. 56496 Survey held at on the Wood, Iron or Steel Le R. "Leekskill" Date, First Survey Last Survey 19... (No. of Visits) Master J. W. Atkinson

TONNAGE: GROSS 220 Built at Selby By whom Cochrane & Sons When 1911 MONTH 12

UNDERTONNAGE 216 Owners Stepney Steam Towing Co Ltd (a moor) Port belonging to Hull Owners' Address (S not already recorded in Appendix to Register Book)

Afloat or in Dry Dock? Name of Dock Destined Voyage

DBorDBa feet; uE&B feet; f feet; city tons. FPT tons; APT tons; MT feet tons. Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

Steel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, the inner bottom plating, especially in the boiler space.

Report, No. 31630 Port Hull. CHARACTER, * for Special Survey, Date of last Survey and of Periodical Surveys. Years elapsed since last survey. Machinery and Boiler Surveys (including date of N.B., if any). +100 A.1. Stm Grawler 4.19. SS Hull No 1-16. +LMC6, 16. B84, 19. T.S. 1, 20. Society's Freeboard (if assigned) as painted on Ship and now verified

where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why lined? Was a damage report made by anyone else? If so, by whom?

EXAMINATION AS PER RULE, FOR

REPAIRS :-	Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items :-
Examined or Repaired								
Examined in place								

OF THE	Stringers	Dblng. Plates under Sounding Pipes	Copper, or Y.M. of Wood Vessels
Inner Bottom Plating	Engine Room Skylights	Copper, or Y.M. of Wood Vessels	(State if on Felt.)
State if Tanks have been examined inside	Coal Bunkers, Open'gs, Lids, &c.	When put on, Month	Year
State if Tanks now tested	Scuppers	Boats	
Bulkheads	Cargo Hatchways	Masts, Yards, &c.	
Ceiling	Hatches	Condition, how ascertained	
Cement or Asphalt (State which.)	Planking of Wood Vessels	(State if wedges removed)	
Rudder	Caulking ditto	Sails	
Steering gear and its connections	Treenails ditto	Equipment letter	
Windlass	Breasthooks & Stemson ditto	Anchors, No. of	
Have Pumps now been examined and found efficient?	Transoms, Pointers, & Crutches ditto	Cables (State if now ranged)	
Have Sluice Valves now been examined and found efficient?	Timbers of Frame at openings ditto	length size (on board)	
Have Watertight Doors now been examined and found efficient?	Ditto ditto at other places ditto	Rule length size	
	Stringers, Clamps & Shelves ditto	Hawser & Warps	
	Salting ditto (State if examined.)	Standing & Running Rigging	

Observations, Opinion as to Class, Recommendation, &c.:-

Whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, for example:— "to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1, 15, and the notations of ss No. 1-15 and pnd15, &c."

Fees applied for, Received by me, Surveyor to Lloyd's Register of Shipping.

Committee's Minute Character Assigned

COPY

Lloyd's Register

