

be made in the Register Book in the case of this vessel.

S.S. "Robin Gray."

It is concluded that a set of liners for adjusting block, and 1 Bucket & rod for lubricating pump have been placed on board, but as these items are not included in the list of spare gear, it is submitted the Seattle Surveyors be requested to state if this is so.

8/10 12/4/20

JWD.

W.H.

10/3/20

005443-005466-0037

005443-005466-0037

*If of iron, state whether scrap or painted