

Chief Surveyors 3.117

Received from Chief Surveyors

EL'S NAME Shells Niels Nielsen

Report Sea

No. 472

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement." - Extract from Sub-Committee's Report, 24/5/02.)

of Survey 1st Sub-

When due

- * 100 A-1. (Steel)
- 2 DG (Steel)

Cell DB 355' 1198E. F.P.T. 1206 A.P.T. 1406

FK. One BH in fore hold + One BH in after hold dispensed with, 5 BH only
can. accep. P 44 B 115. F 47

M
4.17

The Surveyors should be informed it is concluded 2 side stringers are fitted throughout the vessel but they should state if this is so.

The Surveyors should also be requested to amend the approved plans in regard to the arrangement of web frames + string beams fitted in the Engine + Boiler space before forwarding same with the 1st Sub report of the sister vessel.



© 2021

Lloyd's Register Foundation

006067-006079-0105