

N.N. "RUPAVATI"

(Received at London Office)

No. 84503

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report 19... When handed in at Local Office 19... Port of London

No. in Reg. Book 28565 Survey held at on the Head, Iron or Steel Twin S.S. S. "Repton" Date, First Survey Last Survey 19

By whom A.J. Inglis Ltd. Master

Built at Glasgow By whom A.J. Inglis Ltd. When 1919 9

Owners Bombay S.N. Co. Ltd. Port belonging to Bombay

DK. 092 320 Owners' Address (if not already recorded in Appendix to Register Book)

Keel Afloat or in Dry Dock? Name of Dock Destined Voyage

Cell DBor DBa feet; uE&B feet; f feet; } capacity tons. FPT tons; APT tons; MT feet tons. } Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

CHARACTER: For Special Survey, Date of last Survey and of Periodical Surveys. Years Assigned and expired. Machinery and Boiler Surveys (including date of N.B., if any).

Report, No. 10817 Port Lon.

For Government Service 12.20. 2. Water Tube Boilers T.S. 12.20 (CL) Society's Freeboard (if assigned) as painted on Ship and now verified

Was a damage report made by anyone else? If so, by whom?

OR EXAMINATION AS PER RULE, FOR

OF DAMAGE REPAIRS :-	Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items :-
... ..								
... ..								
... ..								

CONDITION OF THE	Stringers	Dblng. Plates under Sounding Pipes	Copper, or Y.M. of Wood Vessels
Decks	Inner Bottom Plating	Engine Room Skylights	(State if on Felt.)
	State if Tanks have been examined inside	Coal Bunkers, Open'gs, Lids, &c.	When put on, Month Year
	State if Tanks now tested	Scuppers	Boats
	Bulkheads	Cargo Hatchways	Masts, Yards, &c.
	Ceiling	Hatches	Condition, how ascertained
	Cement or Asphalt (State which.)	Planking of Wood Vessels	(State if wedges removed)
	Rudder	Caulking ditto	Sails
	Steering gear and its connections	Treenails ditto	Equipment letter
	Windlass	Breasthooks & Stemson ditto	Anchors, No. of
	Have Pumps now been examined and found efficient?	Transoms, Pointers, & Crutches ditto	Cables (State if now ranged)
	Have Sluice Valves now been examined and found efficient?	Timbers of Frame at openings ditto	length size
	Have Watertight Doors now been examined and found efficient?	Ditto ditto at other places ditto	(on board) Rule length size
		Stringers, Clamps & Shelves ditto	Hawser & Warps
		Salting ditto (State if examined.)	Standing & Running Rigging

Observations, Opinion as to Class, Recommendation, &c.:-

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon survey, thus, for example: "to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of 1,15," or "to remain as classed and to have record of survey, 1,15, and the notations of ss No. 1-15 and ptND15, &c."

(per Section 28)	Fees applied for,
Damage or Repair Fee (if any) (per Sec. 29)	19
Travelling Expenses (if chargeable)	19
Second Surveyor's Fee (if any)	

Committee's Minute WFD 3 AUG. 1921 Withdraw Class Character Assigned. Surveyor to Lloyd's Register of Shipping. General Committee Thursday 14th Lloyd's Register Decision of Classing Foundation Comee. confirmed

In Certificates registered? If so, to be sent to

02667-006079-0141