

2126.57

2nd Number

25732

(Where necessary to be entered in Reg. Book.)

Discharge

Surveyors 5. 9. 06

Received from Chief Surveyors

AMELLE Triple S. Turbine S. "St. George" Report Lw. No. 58263

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

Cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

First entry

When due

+ A1 ("Steel") "Shelter deck with freeboard".
"Irish Channel Service".

2 DR (M & S - WS) & Shelter DR (M & S - ~~Deck~~ S)

W. B = Cell DB u E 34' 52" D. Tanks f 20' 160 t

FK 98H Asp. Dlog. A & CP ~~24' 160'~~ F 45'C. K. J.
5/9/06

should be pointed out to the Principal Principal Surveyor that the
of the Vessel in the Committee's minute in the report should be
1 "Shelter deck with freeboard", "Irish Channel Service".

2 should be asked to state whether the double bottom under the
is constructed on the cellular system.



© 2020

Lloyd's Register
Foundation

006111-006125-0193

* If iron or steel deck, state if whole or part, and if wood deck

in Hold	Fore Body	No. and spacing	2 1/2 dia	48	2 1/2 dia	48

Number.

STIFFENERS.