

F.A."TEXOL".- Messrs.Workman Clark & Co's No.368.

A letter has been received from the Belfast Surveyor in which it is stated that the Admiralty have ordered the 5½" stream anchor wire presently on board the ship to be returned to the dockyard. He further states that this wire is required by the Society's Rules for classification, but there are two 3" and two 4" wires on board, and the towlines, hawsers and warps are complete apart from the above.

It is submitted the Surveyor be requested to forward a complete list of the equipment as supplied to this vessel, giving the numbers & weight of each of the anchors, and the length and size of the cables, towlines, etc.

16.2.17.

W.C.



© 2021

Lloyd's Register
Foundation