

to Chief Surveyors

Received from Chief Surveyors

SSEL'S NAME **Steel S.S. "FEDERAL".**

Report *L. J. H.*

No. **158874**

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 34/5/92.)

Particulars of Survey

When due

The anchors have been tested by the Surveyors to the American Bureau of Shipping, and the chain cable at Netherton. The Downton pump and kedge anchor have been dispensed with as a War Emergency Measure.

- * 100 A.1. (Steel) Shelter Deck with freeboard.
- 1 Deck (Steel) and Shelter Deck (Steel) and Webframes.
- Longitudinal framing.

Cell DB. 331' 1512t. FPT 187t. APT 175t.

FK. 7 BH. to Shelter Deck. Cem. Lloyd's CP. P45', B110', F38' on shelter deck.

[Handwritten signature]

2. 1. 19.



© 2021

Lloyd's Register Foundation

006175-006188-0247