

by the Committee to this vessel, have been correctly marked on the vessel's sides,

006189-006203-0355

2nd 5, 19.

1

Sent to Chief Surveyors

Received from Chief Surveyors

VESSEL'S NAME STEEL S.S. "ANACONDA"

Report N.Yk.

No. 17563

**For the CHIEF SHIP SURVEYOR**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement." - Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

When due

The Downton Pump has been dispensed with for the present.  
Chain Cables of Cast Steel.

\* 100 A.1. (steel) "Shelter Dk with Freeboard"

1 Dk (steel) and Shelter Dk (steel) & Webframes.

Longitudinal Framing.

Call DB 331 1512t. FPT 187t. APT 175t.

FK. 70Hts Shelter Dk. jk.com. AYC.P. P45, B 110' F38' on Shelter Dk.

This included the links of Chain Cables are as required for Cast Steel Cables, but the Surveyors should be requested to state if this is so.


2-12-19

Instructions

date

54/4  
6 x  
1/2 x 50  
3.4  
3.2  
3.30

*Handwritten signature*



© 2021

Lloyd's Register  
Foundation