

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report 19... When handed in at Local Office 19... Port of London

No. in Survey held at Reg. Book. 15905 on the Wood, Iron or Steel S. S. CAPELHALL Date, First Survey Last Survey 19... (No. of Visits) Master Blyth S.B.C. Ltd. When 1901 10

TONNAGE:- Built at Blyth By whom Blyth S.B.C. Ltd. Port belonging to Q.M.H.
GROSS 2174 Owners Nairai Kamin K. K.

UNDER DE. 2015 Owners' Address
NET 1378 (if not already recorded in Appendix to Register Book).
Surveyed Afloat or in Dry Dock? Name of Dock Destined Voyage Q.M.H.

WB=Cell DBorDBa feet; uE&B feet; f feet; } Particulars of Classification (which must be inserted
total capacity tons. FPT tons; APT tons; MT feet tons. } precisely as in Register Book & Supplements).

N.B.—All alterations in the existing records should be underlined.
If the Vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, and of the inner bottom plating, especially in the boiler space.

Report, No. 677 Port Alx
CHARACTER. * for Special Survey. Date of last Survey and of Periodical Surveys. Years assigned how long. Machinery and Boiler Surveys (including date of N.B., if any).
+100A1 7.22. +LMC. 2.20
RS. No. 3-8-10. BS. 1.21
RS. No. 2.20. TS. 2.23 cl

Society's Freeboard (if assigned) as painted on Ship and now verified }ft.....ins.

Where cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined?
Was a damage report made by anyone else? If so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE, FOR

THE GREAT NORTHERN LLOYD'S REGISTER LONDON

OF DAMAGE REPAIRS :-	Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items :-
red								
red and Faired or Repaired								
or Repaired in place								

CONDITION OF THE	State if Tanks have been examined inside	Dbng. Plates under Sounding Pipes	Copper, or Y.M. of Wood Vessels (State if on Felt.)
Decks	State if Tanks now tested	Engine Room Skylights	When put on, Month Year
Bulkheads		Coal Bunkers, Open'gs, Lids, &c.	Boats
Ceiling		Scuppers	Masts, Yards, &c.
Cement or Asphalt (State which.)		Cargo Hatchways	Condition, how ascertained (State if wedges removed)
Rudder		Hatches	Sails
Steering gear and its connections		Planking of Wood Vessels	Equipment letter
Windlass		Caulking ditto	Anchors, No. of
Have Pumps now been examined and found efficient?		Treemails ditto	Cables (State if now ranged)
Have Sluice Valves now been examined and found efficient?		Breasthooks & Stomson ditto	length size (on board)
Have Watertight Doors now been examined and found efficient?		Transoms, Pointers, & Crutches ditto	Rule length size
Have Ventilators and their Coamings been examined and found efficient?		Timbers of Frame at openings ditto	Hawser & Warps
		Ditto ditto at other places ditto	Standing & Running Rigging
		Stringers, Clamps & Shelves ditto	
		Salting ditto (State if examined.)	

Observations, Opinion as to Class, Recommendation, &c.:-
State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon survey, thus, for example:—"to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of 1,15," or "to remain as classed and to have record of survey, 1,15, and the notations of ss No. 1-15 and ptND15, &c."

Section 20	Fees applied for,
or Repair Fee (if any)	19
charges (if chargeable)	19
Fee (if any)	

Surveyor to Lloyd's Register of Shipping.
General Committee
Thursday, 3rd January 1924
Classing Committee's decision confirmed
Lloyd's Register Foundation
006387-006400-0202
FRI, 25 DEC. 1923
Escpunge class
with Red line
"Kobe"