

9 - AUG 1945

"EMPIRE LIDDELL"

Fre. 134.

BS due 2.45 held, Screw Shaft examined and machinery generally examined.


Slack stern bush renewed and minor repairs effected.

Electrical installation megger tested.

Insulation of armature and field coils found defective. No facilities at that port to effect repairs, new parts have been ordered. The Surveyor recommends the dynamo which is efficient meanwhile be repaired at earliest opportunity.

It is submitted that this vessel is eligible for the record BS 6.45 S 3.45 Examined 6.45 subject as recommended.

Note 2SB 180 lbs. CL.



Recd.
8.8.45

006401-006406-0189