

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report 19... When handed in at Local Office 19... Port of London

No. in Reg. Book. Survey held at Date, First Survey Last Survey 19

19804 on the Wood, Iron or Steel Sc. Sr. Janine Master

TONNAGE: Built at Toledo, Ohio By whom Toledo S.B. Co. When 1917 7

GROSS 2034 Owners Soc. Auxiliaire d'Importations et de Transports Port belonging to Rouen

UNDER DEK 1213 Owners' Address

NET 1658 (if not already recorded in Appendix to Register Book).

Laid Afloat or in Dry Dock? Name of Dock Destined Voyage

Cell DBor DBa feet; uE&B feet; f feet; } Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

Capacity tons. FPT tons; APT tons; MT feet tons. } CHARACTER. X for Special Survey. Date of last Survey and of Periodical Surveys. Year Assigned now assigned Machinery and Boiler Surveys (including date of N.B., if any).

Report, No. 41886 Port Off

All alterations in the existing records should be underlined. The Vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, and of the inner bottom plating, especially in the boiler space. Society's Freeboard (if assigned) as painted on Ship and now verified

In cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why

Were declined? Was a damage report made by anyone else? If so, by whom?

OR EXAMINATION AS PER RULE, FOR

DAMAGE REPAIRS :—		Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items :—																																					
... ..																																														
1 Paired or Repaired																																														
paired in place																																														
ION OF THE		Stringers	Inner Bottom Plating	State if Tanks have been examined inside	State if Tanks now tested	Bulkheads	Ceiling	Cement or Asphalt	(State which.)	Rudder	Steering gear and its connections	Windlass	Have Pumps now been examined and found efficient?	Have Sluice Valves now been examined and found efficient?	Have Watertight Doors now been examined and found efficient?	Dblng. Plates under Sounding Pipes	Engine Room Skylights	Coal Bunkers, Open'gs, Lids, &c.	Scuppers	Cargo Hatchways	Hatches	Planking of Wood Vessels	Caulking ditto	Treenails ditto	Breasthooks & Stemson ditto	Transoms, Pointers, & Crutches ditto	Timbers of Frame at openings ditto	Ditto ditto at other places ditto	Stringers, Clamps & Shelves ditto	Salting ditto	(State if examined.)	Copper, or Y.M. of Wood Vessels (State if on Felt.)	When put on, Month	Year	Boats	Masts, Yards, &c.	Condition, how ascertained	(State if wedges removed)	Sails	Equipment letter	Anchors, No. of	Cables (State if now ranged)	„ length size (on board)	„ Rule length size	Hawser & Warps	Standing & Running Rigging

General Observations, Opinion as to Class, Recommendation, &c.:— State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:— "to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1, 15," or "to remain as classed and to have record of survey, 1, 15, and the notations of ss No. 1-15 and pnd15, &c."

Survey Fee (per Section 25) £ : : Fees applied for, 19 : : Received by me, 19 : : Special Damage or Repair Fee (if any) £ : : Travelling Expenses (if charged) £ : : Second Surveyor's Fee (if any) £ : : Committee's Minute

General Committee Thursday 31 October 1917 Lloyd's Register Foundation