

1

Iscland

11/1

Sent to Chief Surveyors _____

Received from Chief Surveyors _____

VESSEL'S NAME STEEL S.S. "ICELAND" Report Phl. No. 3506**For the CHIEF SHIP SURVEYOR ~~CHIEF ENGINEER SURVEYOR~~**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/22.)

Nature of Survey _____

When due _____

The Downton Pump has been dispensed with for the present.
Part of Steel tested by the American Bureau Surveyors.


✱ 100 A.1. (steel)

2 Dks (steel) & Webframes.
MT 27' 846'

Cell DB 338' 1311 t. FPT 120t. APT 143t.

FK 6BH. pl. am. A+CP. P36' B124' F44'

It is concluded the ship bank has been constructed in accordance with an approved plan but the Surveyors should be requested to state if this is so.



© 2020

Lloyd's Register
Foundation

all

2-12-19