

"S. S. Robin Goodfellow"

It is concluded that a bucket & rod for lubricating oil pump, and a set of liners for adjusting block have been placed on board, but as these items are not included in the list of spare gear, it is submitted the Seattle Surveyors be requested to state if this is so.

S/O 8/5/20

JWD M/G 9/4/20