

Surveyors

Received from Chief Surveyors

NAME Steel S.S. "ROBIN GOODFELLOW" Report Sea. No. 933.

For the CHIEF SHIP SURVEYOR XXXXXXXXXXXXXXXXXXXX

cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

When due

The Downton Pump has been dispensed with for the present but it is noted the Owners are agreeable to fit same when requested.

Damage has been sustained through striking pier & some indented bow plating requires to be dealt with.

100 A-1. (steel) "Shelter Dk. with freeboard."

2 Dks (steel) and Shelter Dk. (steel).

} Subject to indented bow plating being dealt with at first convenient opportunity.


Cell DB 352' 1222 t. Dtn 35' 811 t. FPT 91 t. APT 200 t.

FK. 3 BH to Shelter Dk. 4 BH to Upper Dk. pl. conn. A/C.P.

M AEB.
9-4-20

It is concluded the thickness of 2nd Deck stringer angle amidships is as approved and that the workmanship is satisfactory, but the Surveyors should be requested to state if this is so.

9/0 8/5/20



Lloyd's Register Foundation