





Hamburg

Continuation of Report No. 14534 dated 10 March 1921 on the

on the steel screw steamer "Prostafels"

The Bunkers cleared all ceiling removed in same  
 rest remained where found necessary. examined framing  
 plating beams & connections found all in good condition  
 now recoated. Yards tested in way of same.

All double bottom, Yards: Fore & After peak tanks spaced  
 out examined inside now cleaned & recoated, fitted and tested  
 found tight and satisfactory.

Decks, examined found in good condition.  
 Hatchways web plates, fore & after, and hatch ~~ways~~ examined  
 now satisfactory. Astern struts examined found in order.  
 Ventilators, their coverings, and covers examined found  
 satisfactory. Mast, Spars & Rigging examined, wedges  
 removed, rigging stripped at nips turned & splices all now  
 satisfactory.

Windlass examined & cables found 240 fathoms  
 $2\frac{4-3}{16}$  in good condition. Steering gears & steering connec-  
 tions overhauled now satisfactory.

Pumps, water tight doors & general equipment  
 examined found satisfactory.

Repairs Ceiling & Cargo battens partly  
 renewed. Hatches partly renewed.

Geo. Dykes  
 P. Fries.



© 2021

Lloyd's Register  
Foundation

0164 2/2