

s.s. "LILLY MARGRETHE"

This vessel has a donkey boiler on board which has not been surveyed by the Society's Surveyors.

The funnel of this boiler was reported by the Piraeus Surveyors in December, 1924, as passing through the upper starboard side bunker without any insulating material or air space, so causing a grave risk of fire.

The vessel is classed subject to the donkey boiler not being used.

The Bergen Surveyor now reports that when he was on board adjusting the main safety valves the Owner requested him to adjust the donkey boiler safety valves.

He called the Owners' attention to the fact that the vessel's class was subject to the donkey boiler not being used. There was about 100 lb. steam pressure on the boiler at the time.

It is submitted for the consideration of the Committee whether the vessel's class should not now be expunged with a black line.

23. 7. 25.

Lloyd's Register
Foundation