

Subject to repairs to framing in ER. Main locker, side bunker, holds + reserve  
bunker + lower decks, and a shoe plate + *also to No 2 Keel plate from aft at the S.S*

1 AUG 1941 **4**

Inspected by Chief Ship Surveyor \_\_\_\_\_

Received from Chief Ship Surveyor \_\_\_\_\_

VESSEL'S NAME *Atuta Maru.*

Rpt. *Yka.*

No. *7094.*

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement." - Extract from Sub-Committee's Report, 24/5/32.)

Nature of Survey *COMPLETION OF 3<sup>rd</sup> S.S. No. 2 due 9, 40.*

The *3<sup>rd</sup>* S.S. No. *2* partly held at *Yokohama*  
now completed, and the following repairs, <sup>or renewals.</sup> done (due to *Wear & Tear*) :- to  
*a number of main frames, reversed frames, web frames, bulkheads, tank floors,*  
*hank side brackets; + 2<sup>nd</sup> deck plating. + minor items.*

*Vessel placed in dry dock & bottom coated*

*The repairs, as above, have now been dealt with.*

It is submitted the vessel is worthy to remain as classed, with record  
of Survey *5, 41* and notation of - *S.S. No 2-41* as recommended.

*without special Condition.*

*100 A1*  
*5, 41*  
*SS Yka. No 2-41* } *without etc*

*CSM.*



*30-7-41* © 2021

Lloyd's Register  
Foundation