

Sent to Chief Surveyors 8.7.16. Received from Chief Surveyors \_\_\_\_\_  
 VESSEL'S NAME sp. Tung Ling. Report Don. No. 79046.

**For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey Screw shaft. When due 9.15.

The first biennial examination of the screw shaft became due in 9.15.

In reply to an inquiry the Owners now state that it is not desired to retain the classification of the vessel.

It is submitted the vessel's class be withdrawn from the Register Book. & three dots inserted in lieu thereof indicating that the class has been withdrawn at the Owners request.

Withdraw class.  
 Insert . . .

LR © 2021  
 Lloyd's Register  
 Foundation  
 8/7/16  
 E. G. B. J. W. D. P. R. K.