

Twin S.S. "MANILA MARU" Nag.Rpt No.1005

The Nagasaki Surveyor reports that the machinery of this vessel has been built under special survey and in accordance with the Rules except that the screw shafts not fitted with continuous liners are $\frac{1}{2}$ " smaller in diameter than required by the Rules.

Had continuous liners been fitted their diameter would have been in excess of the Rules.

It is submitted that these screw shafts might be accepted in this instance, and the record of

LMC 9.15 be assigned

FD. Ref Mch

It is further submitted it should be pointed out to the Nagasaki Surveyor that the Rule diameter of the screw shafts is 15.79" not 14.86" as given in his report.

ARR

14/10/15.



© 2021

Lloyd's Register
Foundation

006942-006953-0130