

The class is subject to the water gauges valves on the boiler being replaced by cocks at the first opportunity.

4 E

of Engineer Surveyor.....

Received from Chief Engineer Surveyor.....

AME "TINOS" REPORT Pir. No. 5317

the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points noted in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

~~REPAIRS TO ENGINES AND BOILERS DUE TO DAMAGE THROUGH~~

This vessel holds the notation of "Examined L.R. 10.46".

The Committee previously approved for an interim General Examination to be held, valid for six months, with a view to the Special Survey being postponed.

A General Examination has now been held, also the Boiler Survey due 10.47 has also been held.

IT IS SUBMITTED that this vessel is eligible for the Record "Examined L.R. 4.48" (6 months), BS 4.48, subject as above.

Lloyd's Register
Foundation