

5/18

8.

Port Arthur
Rpt. No. 27

"WAR OSIRIS"

It is submitted the Port Arthur
Surveyor be requested to state if the
joints of the liner of the screw shaft
have been butted and burned the
full depth of the liner thickness and
be informed that, if this is the case, the
screw shaft should be described in the
report as being fitted with a continuous
liner the whole length of the stem tube.

16-8-15
RRR
© 2021
Lloyd's Register
Foundation

007301-007311-0085

Vulcanized rubber, double braided, led through galvanized iron conduit. In