

GENERAL REMARKS (State quality of workmanship, opinions as to class, &c.)

These two boilers were examined throughout, tested by hydraulic pressure to 200 lbs per sq in, their scantlings verified with plan submitted & all found in order. Their safety valves were adjusted under steam to 100 lbs per sq in.

[The remainder of the page is mostly blank, with some faint ghosting of text from the reverse side.]

The amount of Entry Fee...	£	See	:	When applied for,
Special	£	mach ^s	:	19
Donkey Boiler Fee ...	£	:	:	When received,
Travelling Expenses (if any) £		Report.	:	19

John Houston.
 Engineer Surveyor to Lloyd's Register of British and Foreign Shipping.

Committee's Minute

WED. AUG. 4 1870

Assigned



© 2021

Lloyd's Register
 Foundation

Certificate (if required) to be sent to
 (The Surveyors are requested not to write on or below the space for Committee's Minute.)

pt. 4
 No. in
 Reg. Book
 Master
 Engines
 of Donkey
 Brake
 Nom. H
 60
 T
 ab
 w
 Th
 In
 If
 are
 ves
 to
 the ba
 engine
 the s
 they
 the
 all
 mun
 ked
 of
 of a
 of s
 of s
 mete
 3
 erial
 knes
 il cu
 ge o
 i w
 r su