

Particulars of Examination and Repairs (if any)

"FULGOR".

Gib.3075.

The machinery and boilers of this vessel have been completely opened out and examined.

Screwshaft, propeller and stern tube damaged by sabotage now renewed and alignment of shafting checked.

Some screw stays in the donkey boiler are wasted and the boiler is not to be used until these stays have been renewed.

The impeller casing of the circulating pump is corroded and is recommended to be again examined at the reclassification survey.

IT IS SUBMITTED action be deferred pending receipt of report from Genoa.



*Recll*  
5.12.45

© 2020

Lloyd's Register  
Foundation

007496-007505-0207